


DUAL-CONTROL CAMELS A PHOTOGRAPHIC STUDY



*F1946 of 5 TS AFC is shown under erection or repair in the header photograph. That at the right shows it fully assembled and reveals that, as with such machines converted at Montrose, its induction pipe was not raised. F1946, a converted Boulton & Paul machine, had enlarged cut-outs in its centre-section.
:CCI Archive*



*B7239 of 56 TDS at Cranwell conformed more closely to the original conversion but had only a single pitot head.
:CCI Archive*